

O-6 OSCILLOSCOPE PARTS LIST

Part Parts No. Per Kit	Description	Part Parts No. Per Kit	Description
Resistors		Pilot Light Assembly	
O14	3 470 ohms	O40	1 Nut
T10	1 3300 ohms	O41	1 Bushing
O140	1 6800 ohms	O42	1 Jewel
O11	1 10 K ohms	O52	1 Socket
FM36	1 27 K ohms		
BV23	1 33 K ohms	Knobs-Terminals	
K34	5 220 K ohms	O51	10 Pointer Knobs
SG54	5 390 K ohms	O48	7 Binding Posts
O135	2 680 K ohms	V77R	1 Red Banana Jack
O10	4 3.3 megohms	M28	1 Banana Jack Insert.
O116	1 4700 ohms 2 watt		
G18	2 47 K ohms 1 watt	Screws-Nuts-Washers	
O136	1 1 Megohm 2 watt.	G31	4 4-40 Screws
Condensers		O31	46 6-32 Screws
SG55	2 4-30 MMF Trimmer	G52	4 8-32 Screws
TS50	1 35 MMF	O30	2 10-24 Handle Screws
O137	2 82 MMF	O102	4 #6 Sheet Metal Screws
O138	1 500 MMF	MT12	4 4-40 Nuts
TS36	1 680 MMF	S22	53 6-32 Nuts
V26	1 .003 MFD	TP16	4 8-32 Nuts
T13	2 .01 MFD	O33	10 Control Nuts
O24	1 .01 MFD 1000 V.	O107	1 Condenser Mounting Nut
O25	3 .02 MFD	TS72	46 #6 Lockwashers
O49	2 .1 MFD	BR36	4 #8 Lockwashers
O97	2 .25 MFD	O101	10 Control Lockwashers
O115	1 .5 MFD	O28	10 Nickel Washers
O139	1 .25 or .5 MFD 1500 V.	O26	5 Fibre Shoulder Washers
T40	1 10 MFD 25 V.	O27	5 Fibre Flat Washers
O127	1 20+20+10+10 MFD 450 V.	O37	7 Solder Lugs
Controls-Switches		O44	1 Speednut for Jack.
SW18	2 300 ohm Controls	Sheet Metal Parts	
O129	1 5000 ohm Control	O85C	1 Chassis
O130	1 50 K ohm Control	O86C	1 Panel
O131	1 200 K ohm C.T. Control	O65L	1 Panel Bracket
O59	1 250 K ohm Control	O65R	1 Panel Bracket
O132	1 500 K ohm Control	O70A	1 CR Tube Bracket
O112	1 250 K+1 meg Control	O80A	1 CR Tube Panel Ring
O111	1 5 pos. Rotary Switch	O126	1 CR Tube Shield
PS18	1 SPDT Rotary Switch	O134	1 Shield Mounting Strap
G59	2 DPDT Slide Switches	O128	2 CR Tube Mtg. Clamp
O94	1 SPST Slide Switch	O133	2 Trimmer Mtg. Bracket
Tubes-Lamp		O88	1 Cabinet
A48	3 6J5 or 6J5GT Tubes	O79	1 Handle
T38	4 6SH7 or 6SH7GT Tubes	Miscellaneous	
O66	2 5Y3GT Tubes	O125	1 Power Transformer
O87	1 5BP1 or 5BP4 or 5GP1 Tube	G40	1 Condenser Mounting Wafer
O39	1 #47 Pilot Lamp.	O63A	1 Fuse Block
Sockets-Terminal Strips		O63B	1 Fuse 1/2 A - 250V.
AR32	9 Octal Tube Sockets	O82	1 Grid Screen
O55	1 CR Tube Socket	O34	8 Rubber Feet
S32	4 2 lug Terminal Strips	O35	1 3/8 " Grommet
SW37	2 3 lug Terminal Strips	O36	1 3/4" Grommet
O114	1 4 lug Terminal Strip	O78	1 Line Cord
		O77	1 Length Hookup Wire
		O81	1 Length Spaghetti.